

Ambient Thermometer / Hygrometer Selection Guide

Model		Retail	Internal Temp	Min-Max Memory	External Temp	Internal RH	Min-Max Alarms	External RH	Special Features
Alarm Thermometer 800040R		\$19.00	•	•	•		•		Alarm
Large Display Indoor/Outdoor Thermometer 800015		\$22.50	•	•	•				Large Display
Wireless Thermometer Set 800025		\$26.00	•	•	•		•		Wireless Sensor
Mini Humidity/Temp Monitor 800017R		\$27.00	•	•		•			Mini Size
Alarm Thermometer/ Hygrometer 800041R		\$28.00	•	•		•	•		Alarm
Humidity/Temp Monitor 800016		\$39.00	•	•		•			Large & Time Display
Remote Alarm RH/Temp Monitor 800039		\$47.00		•	•		•	•	Alarm
Wireless Thermo/ Hygrometer Set 800029		\$51.00	•		•	•		•	Wireless Sensor
Remote RH/Temp Monitor 800027		\$58.00		•	•			•	Large Display



REMOTE RH / TEMPERATURE MONITOR 800027

The remote ambient temperature/RH sensor is mounted on a cord over 7' long. Place the highly accurate sensor inside a desiccator, refrigerator, drying or other environmental chamber and view simultaneous displays of temperature and RH outside on the large LCD. Recalls minimum and maximum readings on both parameters. °C and °F selectable. Stands or wall mounts. Dim: 4 1/4" x 3 3/4" x 7/8" (110 x 97 x 20 mm). Weight: 6 oz (170 g).



With NIST traceable certificate of compliance 800027C

REMOTE ALARM RH / TEMPERATURE MONITOR 800039

The remote ambient temperature/RH sensor is mounted on a cord over 7' long. Place the highly accurate sensor inside a desiccator, refrigerator, drying or other environmental chamber and view displays of temperature or RH together with their min-max readings on the monitor outside. Select °C or °F and minimum and maximum temperature and RH alarms. When these parameters are exceeded an audible alarm sounds. Stands or wall mounts. Dim: 4 1/8" x 2 3/4" x 6/8" (105 x 70 x 20 mm). Weight: 3 oz (85 g).



With NIST traceable certificate of compliance 800039C



	Range	Resolution	Accuracy
Temperature	-10~50°C -14~122°F	0.1°C/F	±1°C ±2°F
Humidity	20~99%	1%	±4% f.s.